

Allows you to switch between Whirl-A-Way and Wand without having to shutdown the unit.



Max Pressure4,000 PSIMax Temperature180 °FOutlet3/8" Quick Connect PlugInlet3/8" Quick Connect CouplerWeight2.28 lbs		
Outlet3/8" Quick Connect PlugInlet3/8" Quick Connect Coupler	Max Pressure	4,000 PSI
Inlet 3/8" Quick Connect Coupler	Max Temperature	180 °F
· · · · · ·	Outlet	3/8" Quick Connect Plug
Weight 2.28 lbs	Inlet	3/8" Quick Connect Coupler
	Weight	2.28 lbs



#	Part#	Replacement Part
1	85.790.004	Rotary Head
2	85.791.009	Rotary Arm - 16″ 2 Arm
	85.790.010	Rotary Head Repair Kit
3		
4	85.790.012	Nylon Brush Skirt - 16″
	05.7 70.012	Nyion brash skill - To



#	Part#	Replacement Part
1	85.790.021	Rotary Head
2	85.791.016	Rotary Arm
	85.790.022	Rotary Head Repair Kit
3		
4	85.790.024	Nylon Brush Skirt - 12″
		· · ·



Part#	85.202.017	
Max Pressure	4,000 PSI	
Max Temperature	180 °F	
Max Flow	8 GPM	
Outlet	1/4" FNPT	
Inlet	3/8" FNPT	
Weight	1.35 lbs	