



**Cleated Outsole:**  
Spits out debris for good slip resistance.



**Cross Hatch Outsole:**  
Tread design covers more surface area for good slip resistance.

## SIZING

Overshoe Size	Men's
Small	6½ - 8
Medium	8 - 9½
Large	9½ - 11
X Large	11 - 12½
2X Large	12½ - 14
3X Large	14 - 15½

**Ideal Applications:** Food Processing, Transportation, Utilities, Construction, General Industry, Municipalities, and Agriculture.

**Chemical Resistance:** Acids, alcohols, bases, and diluted water solutions of most chemicals that are water soluble. Not recommended for constant contact with petroleum and oil based products.



## RUBBER OVERSHOES

**HI-TOP WORK RUBBER – COVERS WORK SHOE UP TO THE ANKLE**

1300 | Black – Cleated Outsole | S – 3XL

**10" WORK BOOT – MOLDED IN BUTTON FOR SECURE CLOSURE**

1400 | Black – Cleated Outsole | S – 3XL

**17" KNEE BOOT – MOLDED IN BUTTON FOR SECURE CLOSURE**

1500 | Black – Cross Hatch Outsole | S – 3XL