




Cleated Outsole:

Spits out debris for great traction.

Ideal Applications: General purpose in Agriculture, Industry, and Construction.

Chemical Resistance: Fats, certain acids, hydrocarbons, caustics, and other chemicals.



**GENERAL PURPOSE KNEE BOOTS
CLEATED OUTSOLE**

■ ■ 31144	Black Upper – Black Sole – Ht. 15" – Plain Toe	3 – 14
■ ■ 31244	Black Upper – Black Sole – Ht. 15" – Steel Toe	4 – 14