Soap For Hope

Touching a Life one Bubble at a Time

EnviroSpec DONATES

100% OF PROFITS

from chemical sales to





CONTAINS SUPERFLO POLYMER™ GLOSS ENHANCERS BLEACH STABLE SURFACTANTS

DESIGNED AND BUILT EXCLUSIVELY FOR SURFACES CONTAINING MOLD, MILDEW AND GENERAL 'FALL-OUT' POLLUTANTS SUCH AS ACID RAIN AND EXHAUST CARBON

MIXING INSTRUCTIONS:

Remember - warm water (not to exceed 120°F) will always make powders go into solution easier. If cold water is used manual agitation may be necessary.

EnviroSpec products are manufactured in such a manner as to insure that once the product is totally dissolved that it will stay in solution for a very long period of time.

When mixing, fill a clean poly drum approximately 50% full of warm water as outlined above and place the nozzle of a high pressure washer close to the bottom and continue filling while adding the powder slowly. When the drum is 80% full stop filling, pour in the 1 gallon container of liquid and continue filling until drum is full. Allow to cool down befroe using.

Health & Safety Information EFFECTS OF OVER EXPOSURE

- Ingestion: Damage to renal system may occur
- Eyes: Causes severe eye irritation
- Skin: Causes skin irritation
- · Inhalation: Causes respiratory tract irritation

In case of Emergency call CHEMTREC @ 1-800-424-9300

Visit our web site for a variety of washing instructions and technical information www.envirospec.com

Emergency First Aid Procedures:

- Ingestion: Dilute the alkali by giving water or milk immediately and allow vomiting to occur. Examine victim for possible corrosive injury to mouth and throat and irrigate the areas with a 1% Acetic Acid until alkali is completely neutralized. Avoid gastric lavage or emesis. (Dreisbach, Handbook of Poisoning, 11th Edition). Maintain airway and treat shock. If vomiting occurs, keep head below hips to help prevent aspiration. Get medical attentionimmediately.
- **Eyes:** Flush with copious amounts of water until all material is removed. If irritation develops or persists, get medical attention.
- **Skin:** Thoroughly wash exposed area with soap and water. Remove contaminated clothing
- Inhalation: Remove to fresh air. If breathing is difficult, oxygen may be given, preferably with a physician's advice. If not breathing, give artificial respiration, preferably mouth-to-mouth. Get immediate medical attention.

This quality product is Manufactured by:

EnviroSpec

a Division of Hi Tech Jetting Technologies, Inc.

751 MLK Hwy. • Homerville, GA 31634

For further information call: 1-800-346-4876

READ & UNDERSTAND

the Material Safety Data Sheet Prior to Use If no MSDS is present call 1-800-346-4876

For Industrial or Professional Use Only **KEEP OUT OF REACH OF CHILDREN**