# **PLEX-MASTER**





and hardeners that will enhance the appearance of both Vinyl and Aluminum as well as retard mildew reformation on all surfaces, including wood.

# Formulated for the Exterior House Wash Industry

## This Product Contains: "High Yield Gloss Enhancers"

This Quality Product is Manufactured by:

a Division of: Hi Tech Jetting Technologies, Inc. 1316 Route 202 • Greene, ME 04236

For further information call: 1-800-346-4876

#### **DISTRIBUTED BY:**

# SURFACE SEALANT WITH MILDEW FORMATION RETARDANT

**BLENDING INSTRUCTIONS** Pre-mix 5 gallons of **Plex-Master** with 20-25 gallons of water. Further dilute by means of a down stream injector at a ratio of 20 parts water to 1 part **Plex-Master**.

### **USE INSTRUCTIONS:**

Work in small sections to avoid product from drying on the surface before rinsing. Rinse thoroughly.

**Plex-Master** should not be applied to any surface if the homeowner is planning on painting during the next 12-15 months. Because of the unique hardeners used in the formulation, **Plex-Master** will remain on the surface for a long period of time. It is recommended that you re-clean the surface using **Prodigy** before you customer paints. By doing so your customer can be assured that all of the **Plex-Master** has been removed and the paint will adhere to the surface.

Mildew will be much easier to remove when there is a coating of Plex-Master on the substrate. In most cases, the homeowner will be able to keep the surface alive and free of mildew with a weekly rinse with the garden hose.

### **Emergency First Aid Procedures:**

• **Ingestion:** Low order of toxicity. First aid is normally not required.

• **Eyes:** Irritating, and may injure eye tissue if not removed promptly. Immediately flush eyes with large amounts of water for at least 15 minutes. Get prompt medical attention.

• **Skin:** Low order of toxicity. Irritating. Flush with large amounts of water; use soap if available. If irritation persists, seek medical attention.

• Inhalation: Remove to fresh air. If breathing is difficult, oxygen may be given, preferably with a physician's advice. If not breathing, give artificial respiration, preferably mouth-to-mouth. Get immediate medical attention.

### READ & UNDERSTAND the MSDS Prior to Use If none is present call 1-800-346-4876 For Industrial or Professional Use Only KEEP OUT OF REACH OF CHILDREN







1-800-346-4876

ENVIBOSPEC